

# HYUNDAI-CRYSTAL Over-The-Air (OTA) Software Upgrade Procedure





## HYUNDAI -CRYSTAL

### Over-The-Air (OTA) Software Upgrade Procedure

#### Part I – Software Upgrading

1. Press "Menu", select "Installation" and press "Ok"
2. Select "Software Update" and press "Ok"



3. Select "Start" and press "Ok"
4. A "Please Wait" window will appear (Do not EXIT or CANCEL)





5. A "New Software Window" will appear, select "Immediate" and press "Ok"
6. "Software Download" will start (Do not unplug power cable)




7. A status bar will appear to monitor progress of upgrading

8. Wait until progress has reached 100% to signify completion of software update



9. After software update has been completed, the STB or Box will reboot. A "New Software Loaded!" window will appear. Press "Ok"

10. The STB or Box has been upgraded and will return to the channel you are watching



## Part II – Scan Channels

1. Press "Menu", select "Installation" and press "Ok"

2. Select "TP Edit/Scan" and press "Ok"




3. Select "Scan" and press "Ok"

4. Select "All Network Scan Start" and press "Ok" to start channel scan



5. The scan window will appear to show the channels being captured and progress of scanning.

6. After scanning has reached 100%, a "Scan is Done" window will appear. Press "Ok" to finish scan.



### Part III – Verify Software Version

1. Press "Menu", select "System Setup" and press "Ok"

2. Select "System Information" and press "Ok"



3. Software Version indicated must be SW 1.15

4. Press "Exit" on the remote control to return to your channel.

